



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 46 Sheridan		District Name Westby K-12 Schools	
Vehicle I.D. # (VIN) - Entire Number 1GBG6P1PXLV110762	Model Year 1990	License # 168	Rated Capacity ***** 41
Chassis Make Chevrolet	Body Make Carpenter	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input checked="" type="checkbox"/> Gas <input type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☒ 1st semester ☐ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 46 Sheridan		District Name Westby K-12 Schools	
Vehicle I.D. # (VIN) - Entire Number 1GBHG31KOTF112352	Model Year 1996	License # 92	Rated Capacity ***** 21
Chassis Make Chevrolet	Body Make Bluebird	Bus Type: (see ? for definition) <input checked="" type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input checked="" type="checkbox"/> Gas <input type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☒ 1st semester ☐ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 46 Sheridan		District Name Westby K-12 Schools	
Vehicle I.D. # (VIN) - Entire Number 1GBHG31R411193041	Model Year 2001	License # 266	Rated Capacity ***** 21
Chassis Make Chevrolet	Body Make Other	Bus Type: (see ? for definition) <input checked="" type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input checked="" type="checkbox"/> Gas <input type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☒ 1st semester ☐ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 46 Sheridan		District Name Westby K-12 Schools	
Vehicle I.D. # (VIN) - Entire Number 1GBHG31R6W1063575	Model Year 1998	License # 190	Rated Capacity ***** 21
Chassis Make Chevrolet	Body Make Bluebird	Bus Type: (see ? for definition) <input checked="" type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input checked="" type="checkbox"/> Gas <input type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☒ 1st semester ☐ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 46 Sheridan		District Name Westby K-12 Schools	
Vehicle I.D. # (VIN) - Entire Number 1GBHG31RX21192025	Model Year 2002	License # 29	Rated Capacity ***** 18
Chassis Make Chevrolet	Body Make Bluebird	Bus Type: (see ? for definition) <input checked="" type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input checked="" type="checkbox"/> Gas <input type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☒ 1st semester ☐ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 46 Sheridan		District Name Westby K-12 Schools	
Vehicle I.D. # (VIN) - Entire Number 2707	Model Year 2005	License # 77	Rated Capacity ***** 22
Chassis Make Chevrolet	Body Make Bluebird	Bus Type: (see ? for definition) <input checked="" type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input checked="" type="checkbox"/> Gas <input type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☒ 1st semester ☐ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 46 Sheridan		District Name Medicine Lake K-12 Schools	
Vehicle I.D. # (VIN) - Entire Number 1FDPB80C3WVA20414	Model Year 1997	License # 201	Rated Capacity ***** 47
Chassis Make Ford	Body Make Amtran	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☒ 1st semester ☐ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 46 Sheridan		District Name Medicine Lake K-12 Schools	
Vehicle I.D. # (VIN) - Entire Number 1FDPB80CIWVA20413	Model Year 1997	License # 27	Rated Capacity ***** 47
Chassis Make Ford	Body Make Amtran	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☒ 1st semester ☐ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 46 Sheridan		District Name Medicine Lake K-12 Schools	
Vehicle I.D. # (VIN) - Entire Number 1FDPB80CP5VA81759	Model Year 1995	License # 306	Rated Capacity ***** 47
Chassis Make Ford	Body Make Amtran	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☒ 1st semester ☐ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 46 Sheridan		District Name Medicine Lake K-12 Schools	
Vehicle I.D. # (VIN) - Entire Number 1FDPJ75AIMVA29940	Model Year 1991	License # 138	Rated Capacity ***** 47
Chassis Make Ford	Body Make Ward	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☒ 1st semester ☐ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 46 Sheridan		District Name Medicine Lake K-12 Schools	
Vehicle I.D. # (VIN) - Entire Number 1FDPJ75C0PVA25528	Model Year 1993	License # 146	Rated Capacity ***** 47
Chassis Make Ford	Body Make Amtran	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☒ 1st semester ☐ 2nd semester
Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 46 Sheridan		District Name Medicine Lake K-12 Schools	
Vehicle I.D. # (VIN) - Entire Number 1FDPJ75C3NVA28789	Model Year 1992	License # 44	Rated Capacity ***** 47
Chassis Make Ford	Body Make Ward	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☒ 1st semester ☐ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 46 Sheridan		District Name Medicine Lake K-12 Schools	
Vehicle I.D. # (VIN) - Entire Number 1FDPJ75C4PVA34393	Model Year 1993	License # 111	Rated Capacity ***** 54
Chassis Make Ford	Body Make Amtran	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☒ 1st semester ☐ 2nd semester
Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 46 Sheridan		District Name Medicine Lake K-12 Schools	
Vehicle I.D. # (VIN) - Entire Number 1GBJ6PIP5LV109699	Model Year 1990	License # 127	Rated Capacity ***** 47
Chassis Make Chevrolet	Body Make Ward	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input checked="" type="checkbox"/> Gas <input type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☒ 1st semester ☐ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 46 Sheridan		District Name Medicine Lake K-12 Schools	
Vehicle I.D. # (VIN) - Entire Number 1GBJ6PIP6KVI12092	Model Year 1989	License # 213	Rated Capacity ***** 47
Chassis Make Chevrolet	Body Make Ward	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input checked="" type="checkbox"/> Gas <input type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☒ 1st semester ☐ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 46 Sheridan		District Name Medicine Lake K-12 Schools	
Vehicle I.D. # (VIN) - Entire Number 1HVBBAAMXYH268216	Model Year 2000	License # 69	Rated Capacity ***** 47
Chassis Make International	Body Make Amtran	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☒ 1st semester ☐ 2nd semester
Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 46 Sheridan		District Name Medicine Lake K-12 Schools	
Vehicle I.D. # (VIN) - Entire Number 4DRBRAAM82B945514	Model Year 2002	License # 260	Rated Capacity ***** 47
Chassis Make International	Body Make International	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☒ 1st semester ☐ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 46 Sheridan		District Name Plentywood K-12 Schools	
Vehicle I.D. # (VIN) - Entire Number 1FDNB80C2WVA08116	Model Year 1997	License # 234	Rated Capacity ***** 47
Chassis Make Ford	Body Make Amtran	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☒ 1st semester ☐ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 46 Sheridan		District Name Plentywood K-12 Schools	
Vehicle I.D. # (VIN) - Entire Number 1FDNJ75C7RVA39050	Model Year 1994	License # 57	Rated Capacity ***** 42
Chassis Make Ford	Body Make Amtran	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☒ 1st semester ☐ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 46 Sheridan		District Name Plentywood K-12 Schools	
Vehicle I.D. # (VIN) - Entire Number 1FDPJ75C7PVA29544	Model Year 1993	License # 96	Rated Capacity ***** 48
Chassis Make Ford	Body Make Amtran	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Wheel Chair Lift Equipped? <input checked="" type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☒ 1st semester ☐ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 46 Sheridan		District Name Plentywood K-12 Schools	
Vehicle I.D. # (VIN) - Entire Number 1FDPJ75C9PVA29545	Model Year 1993	License # 13	Rated Capacity ***** 48
Chassis Make Ford	Body Make Amtran	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☒ 1st semester ☐ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 46 Sheridan		District Name Plentywood K-12 Schools	
Vehicle I.D. # (VIN) - Entire Number 1FDPJ75P2MVA21625	Model Year 1991	License # 97	Rated Capacity ***** 36
Chassis Make Ford	Body Make Ward	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☒ 1st semester ☐ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 46 Sheridan		District Name Plentywood K-12 Schools	
Vehicle I.D. # (VIN) - Entire Number 1FDPJ75P6LVA27846	Model Year 1990	License # 171	Rated Capacity ***** 48
Chassis Make Ford	Body Make Ward	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☒ 1st semester ☐ 2nd semester
Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 46 Sheridan		District Name Plentywood K-12 Schools	
Vehicle I.D. # (VIN) - Entire Number 1FDPJ75P9NVA18707	Model Year 1992	License # 100	Rated Capacity ***** 48
Chassis Make Ford	Body Make Ward	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☒ 1st semester ☐ 2nd semester
Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 46 Sheridan		District Name Plentywood K-12 Schools	
Vehicle I.D. # (VIN) - Entire Number 1HVBBAAM9XH249462	Model Year 1999	License # 80	Rated Capacity ***** 48
Chassis Make International	Body Make Amtran	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☒ 1st semester ☐ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 46 Sheridan		District Name Plentywood K-12 Schools	
Vehicle I.D. # (VIN) - Entire Number 4DRBRAAMX2B947698	Model Year 2002	License # 170	Rated Capacity ***** 36
Chassis Make International	Body Make Amtran	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☒ 1st semester ☐ 2nd semester
Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official _____

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date _____



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 46 Sheridan		District Name Outlook K-12 Schools	
Vehicle I.D. # (VIN) - Entire Number 1FDP175C0PVA02279	Model Year 1993	License # 194	Rated Capacity ***** 30
Chassis Make Ford	Body Make Bluebird	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☒ 1st semester ☐ 2nd semester
Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 46 Sheridan		District Name Outlook K-12 Schools	
Vehicle I.D. # (VIN) - Entire Number 1FDPJ75C9PVA29688	Model Year 1993	License # 160	Rated Capacity ***** 42
Chassis Make Ford	Body Make Bluebird	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☒ 1st semester ☐ 2nd semester
Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 46 Sheridan		District Name Outlook K-12 Schools	
Vehicle I.D. # (VIN) - Entire Number 2GDHG31K1P4509619	Model Year 1993	License # 239	Rated Capacity ***** 22
Chassis Make GMC	Body Make Other	Bus Type: (see ? for definition) <input checked="" type="checkbox"/> A <input type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input checked="" type="checkbox"/> Gas <input type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☒ 1st semester ☐ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date



Linda McCulloch, Superintendent
Office of Public Instruction
PO Box 202501
Helena, MT 59620-2501

MONTANA HIGHWAY PATROL
School Bus Inspection
School Year 2006

State ☐
District ☐
County ☐
Patrol ☐
Contractor ☐

This complete form is required in accordance with Section 20-10-101, MCA. All vehicles not approved on first inspection must be reinspected by the Highway Patrol as soon as all defects are corrected.

Instructions to OPI from School District:

- ☐ This bus has been sold, retired, or is no longer in service. Please delete it from OPI's records.
☐ Please make corrections noted below. Don't black out the error, OPI may need to read it to make the correction.

OPI County # and County Name 46 Sheridan		District Name Outlook K-12 Schools	
Vehicle I.D. # (VIN) - Entire Number 44Z3CFAC6WC973452	Model Year 1999	License # 223	Rated Capacity ***** 42
Chassis Make Freightliner	Body Make Thomas	Bus Type: (see ? for definition) <input type="checkbox"/> A <input type="checkbox"/> B <input checked="" type="checkbox"/> C <input type="checkbox"/> D	
Wheel Chair Lift Equipped? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Wheel Chair Lift Equipped? <input type="checkbox"/> Forward Facing <input type="checkbox"/> Aisle Facing <input checked="" type="checkbox"/> Not Applicable		
Type of Fuel: <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel <input type="checkbox"/> Other	Is Bus: <input checked="" type="checkbox"/> District Owned <input type="checkbox"/> Contractor Owned If contractor owned, contractor's name is:		

INSPECTION

TO BE FILLED OUT BY THE HIGHWAY PATROL

This inspection is for: ☒ 1st semester ☐ 2nd semester

Approved

Approved

Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr	Page No.*	Items listed in the Standards for School Buses in Montana	Yes	No	NA **	Corr
C17	Identification - front					C34	Belt cutter **** attached				
C18	Head lamps					C18	Interior lamps				
C10	Color					C18	Ceiling - interior				
C18	Turn signal lamps - front					C21	Seating				
C18	Turn signal lamps - side (post 1987)					C14	Floor				
C18	Red amber signals - front					C9	Aisle				
C18	Marker lamps - front					C22	Tools - storage				
C18	Windshield					C24	Windows				
C24	Windshield wipers					C13	Warning device				
C20	Exterior mirrors					C13	Buzzer emergency door				
C3	Battery					C12	Emergency door				
C4	Generator or alternator					C18	Red amber signals - rear				
C11	Service door					C18	Turn signal lamps - rear				
C6	Head lamp indicator					C18	Stop lamps				
C6	Horn					C18	Marker lamps - rear				
C20	Interior mirror					C19	Strobe light - rear ***				
C6	Speedometer					C17	Identification - rear				
C2	Brakes					C4	Exhaust system (no leaks)				
C21	Driver seat belt					C5	Fuel tank				
C7	Steering gear					C7	Tires (2/32" rear - 4/32" front min.)				
C13	Fire extinguisher (5 lbs)						Cleanliness				
C13	First aid kit					C22	Stop arm				
C13	Body fluids kit					C5	No trailer hitch				
C11	Defroster						Required by forest regulation:				
C6	Heaters						Shovel (securely fastened)				
C20	Wheelchair forward facing (post 1993)						Axe (securely fastened)				

*Page number reference, Standards for School Buses in Montana (2002 Edition). ****Bus drivers are required to wear lap/shoulder belts - cutter attached nearby driver.

Does not apply. *New buses ordered after 08/15/02. *****Based on original capacity listed on the manufacturers certification tag found inside the bus.

On first inspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Signature of District Official

On reinspection, this bus is:

- ☐ Approved
☐ Not Approved

Inspecting Patrol Officer: _____

Badge No. _____ Date _____

Date